


## CORNER RECORD

Document Number CR 7314City of PiedmontCounty of Alameda, CaliforniaBrief Legal Description BRASS DISKS AT THE SOUTHWEST CORNER OF THE INTERSECTION MORAGA AVENUE AND HIGHLAND AVENUE.

## CORNER TYPE

Government Corner ☐ Control ☒  
 Meander ☐ Property ☒  
 Rancho ☐ Other ☐  
 Date of Survey February 24, 2015

## COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29 ☐ NAVD88 ☐  
 Meas. Units: Metric ☐ Imperial ☐

Corner — Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

TURNED ANGLES WERE MEASURED FROM EACH FOUND MONUMENT TO BE REMOVED BETWEEN TWO FOUND 1/2"

IRON PINS IN MONUMENT WELLS AND TWO SET RIVETS WITH BRASS TAGS STAMPED PLS 8614 TO PRESERVE

MONUMENT LOCATION PRIOR TO REMOVAL BY CONTRACTOR DUE TO CITY OF PIEDMONT HIGHLAND AVENUE - PARK WAY DRAINAGE IMPROVEMENT PHASE I PROJECT.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

FOUND 1-1/2 INCH BRASS DISK STAMPED 2917 SET IN THE CONCRETE GUTTER PAN AND FOUND 3" BRASS DISK

STAMPED "CITY OF OAKLAND SEC. 101 SURVEY STA. C" SET IN THE CONCRETE SIDEWALK AT THE SOUTHWEST CORNER OF THE INTERSECTION MORAGA AVENUE AND HIGHLAND AVENUE.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on May 19, 2015

Signed Anthony G. Cinquini P.L.S. or R.C.E. No. 8614



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 5-28-15

and examined and filed 6-8-15

Signed Russell R. Penland P.L.S. or R.C.E. No. 5726

Title County Surveyor

County Surveyor's Comments \_\_\_\_\_

