


CORNER RECORD

Agency Index BK 105 PG 89
Document Number CR 10967

City of unincorporated County of Alameda, California
Brief Legal Description Fairmont Drive approx. 280' south of Lark Street



CORNER TYPE

Government Corner ☐ Control ☒
Meander ☐ Property ☐
Rancho ☐ Other ☐

Date of Survey January 15, 2018

COORDINATES (Optional)

N. E.

Elevation

Units Metric ☐ U.S. Survey Foot ☐

Horizontal Datum

Zone Epoch Date

Vertical Datum

☐ Complies with Public Resources Code §§8801-8819

☐ Complies with Public Resources Code §§8890-8902

PLS Act Ref.: ☐ 8765(d) ☒ 8771 ☐ 8773 ☐ Other:
Corner/
Monument: ☐ Left as found ☐ Established ☐ Rebuilt ☒ Pre-Construction
☐ Found and tagged ☐ Reestablished ☒ Referenced ☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☐ See sheet #2 for description(s):

FOUND DISK MONUMENTS WITH PUNCH IN MONUMENT WELLS. SET REFERENCE TIES
PRIOR TO CONSTRUCTION.
ALAMEDA COUNTY SPEC. NO. 2327

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on March 3, 2018

Signed Dentse D. Baker P.L.S. or R.C.E. No. P.L.S. #7947



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 25 JANUARY 2018

and examined and filed 4 APRIL 2018

Signed Michael Rubner P.L.S. or R.C.E. No. 6843

Title COUNTY SURVEYOR

County Surveyor's Comment

SPEC 2327

